

COMPLETED

- Underpinning nearing completion
- Wall rough-ins nearing completion

ONGOING

- Rough-ins at first floor Paterno
- Drywall installation at first floor Paterno
- Re-routing existing storm pipe at courtyard
- New MEP installation at first floor offices

UPCOMING

- Continuing lighting fixture rough-ins at Paterno
- Completing courtyard work for micropiles
- Micropile test pile

HANGING DRYWALL AT FIRST FLOOR PATERNO





Egress Framing Modifications at Paterno




Underpinning Nearing Completion



Re-routing Existing Storm Pipe



Lighting Fixture Rough-Ins at Paterno



New MEP Install at First Floor Offices